

**ASBESTOS SURVEY SUMMARY  
PACIFIC UNION COLLEGE  
ANGWIN, CALIFORNIA**

**SUMMARY OF ASBESTOS CONTAINING MATERIAL IN BUILDINGS AND  
BULK SAMPLE ANALYSIS**

**Definition of terms:**

**Friable:** Material that can be crumbled or reduced to powder by hand pressure.

**Nonfriable:** Material that is bonded in an adhesive matrix, or other cementitious material, that does not crumble or reduce to powder by hand pressure.

Building No.: 1

Building Name: **Shopping Center**

Suspect Materials Sampled: Floor tiles, linoleum, mastics, ceiling panels, wallboard, spray-applied acoustic

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Hallway  
Asbestos Content: 10 to 20 percent Chrysotile asbestos.
- 2) **12" x 12" Floor Tile & Mastic** - Type: Nonfriable Location: Market  
Asbestos Content: 1 to 10 percent Chrysotile asbestos.
- 3) **Linoleum & Mastic** - Type: Nonfriable Location: Dairy Cooler  
Asbestos Content: 5 to 10 percent Chrysotile asbestos.
- 4) **Plaster & Paint** - Type: Nonfriable Location: All interior walls  
Asbestos Content: 1 to 5 percent Chrysotile asbestos.

Building No.: 2

Building Name: **Post Office**

Suspect Materials Sampled: Floor tile, mastic, spray applied acoustic, pipe covering, joint & elbow packing, ceiling tiles, duct seam tape

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: lunchroom, locker room, storage room, loading room  
Asbestos Content: 5 to 10 percent Chrysotile asbestos.
- 2) **9" x 9" Green Floor Tile** - Type: Nonfriable Location: throughout building  
Asbestos Content: 1 to 5 percent Chrysotile asbestos (tile), 5 to 10 percent Chrysotile asbestos (mastic).

Building No.: 3

Building Name: **Counseling Center**

Suspect Materials Sampled: spray applied acoustic, yellow linoleum, 24" x 36" ceiling tile

**Asbestos-Containing Materials Found:**

- 1) **Yellow Linoleum** - Type: Nonfriable Location: kitchen, computer office, PR-Reception area  
Asbestos Content: 20 to 25 percent Chrysotile asbestos

Building No.: 4

Building Name: **Dental Building**

Suspect Materials Sampled: Linoleum, mastic, 24" x 36" ceiling tiles

NO ASBESTOS-CONTAINING MATERIALS FOUND

Building No.: 5

Building Name: **Silverado Federal Credit Union**

Suspect Materials Sampled: Floor tile, mastic, ceiling tiles, wallboard, duct tape

**Asbestos-Containing Materials Found:**

- 1) **Silver Duct Tape** - Type: Nonfriable Location: Mezzanine  
Asbestos Content: 40 to 45 percent Chrysotile asbestos

Building No.: 8

Building Name: **Brookside Park Apartments**

Suspect Materials Sampled: spray applied acoustic, linoleum, mastic, plaster, and paint

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: throughout 45 Units,  
Asbestos Content: 5 to 30 percent Chrysotile asbestos
- 2) **Linoleum & Mastic** - Type: Nonfriable Location: entry, kitchen, and bathroom in all 45 units  
Asbestos Content: 40 to 45 percent Chrysotile asbestos

Building No.: 9

Building Name: **Service Station**

NO SUSPECT ASBESTOS-CONTAINING MATERIALS FOUND

Building No.: 11

Building Name: **Press Building**

Suspect Materials Sampled: Floor tiles, mastic, ceiling tile, interior plaster, linoleum

**Asbestos-Containing Materials Found:**

- 1) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: Auto Parts- Warehouse, Preferred Images, Estate Planning  
Asbestos Content: 1 to 20 percent Chrysotile asbestos
- 2) **Red/White Linoleum** - Type: Nonfriable Location: Preferred Images- stairwell  
Asbestos Content: 5 to 10 percent Chrysotile asbestos

Building No.: 12

Building Name: **Custodial Building**

Suspect Materials Sampled: Floor tile, ceiling tile, linoleum, duct insulation, pipe insulation

**Asbestos-Containing Materials Found:**

- 1) **Pipe Covering** - Type: Friable Location: Pipe chase  
Asbestos Content: 15 to 40 percent Chrysotile asbestos
- 2) **Elbow and Joint Packing** - Type: Friable Location: Pipe chase,

- 3) Asbestos Content: 30 to 40 percent Chrysotile asbestos  
**9" x 9" Beige Vinyl Floor Tile** - Type: Nonfriable Location: offices, assembly room, men's restroom Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 13

Building Name: **Laundry and Powerhouse**

Suspect Materials Sampled: Floor tile, mastic, interior plaster

**Asbestos-Containing Material Found**:

NO ASBESTOS-CONTAINING MATERIALS REMAIN

Building No.: 14

Building Name: **Church Sanctuary**

Suspect Materials Sampled: textured spray material, spray applied acoustic, floor tiles, fireproofing

**Asbestos-Containing Materials Found**:

- 1) **Interior Texture Spray** - Type: Friable Location: Ceilings, Walls  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 2) **Spray Applied Acoustic** - Type: Friable Location: hallways, classrooms  
Asbestos Content: 20 to 45 percent Chrysotile asbestos
- 3) **Spray Applied Fireproofing** - Type: Friable Location: HVAC Plenum Areas  
Asbestos Content: 20 to 35 percent Chrysotile asbestos
- 4) **9" x 9" Almond Vinyl Floor Tile** - Type: Nonfriable Location: classrooms, hallways  
Asbestos Content: 1 to 5 percent Chrysotile asbestos (tile), 5 to 10 percent Chrysotile asbestos (mastic)

Building No.: 16

Building Name: **Fisher Hall**

Suspect Materials Sampled: spray applied acoustic, floor tile, mastic, linoleum, pipe covering, duct tape, welding both panels, kiln insulations

**Asbestos-Containing Materials Found**:

- 1) **Brown Spray Applied Acoustic** - Type: Friable Location: 1st floor: lobby, machine and welding shops, 2nd floor: library  
Asbestos Content: 20 to 25 percent Chrysotile asbestos
- 2) **Pipe Covering** - Type: Friable Location: 1st floor: machine shop  
Asbestos Content: 70 to 75 percent Chrysotile asbestos
- 3) **Joint and Elbow Packing** - Type: Friable Location: 1st floor: machine shop, welding shop, auto shop, office  
Asbestos Content: 15 to 30 percent Chrysotile asbestos
- 4) **White Spray Applied Acoustic** - Type: Friable Location: 2nd floor: south corridor,  
Asbestos Content: 20 to 30 percent Chrysotile asbestos
- 5) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: 1st floor: lobby, corridor, classroom, machine shop office, auto shop office and classroom, 2nd floor: headquarters (under carpet), drafting classrooms, laser print classrooms  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 6) **Transite Panels** - Type: Nonfriable Location: welding classroom  
Asbestos Content: 45 to 50 percent Chrysotile asbestos

Building No.: 17

Building Name: **Church (Fireside Room & Youth Chapel)**

Suspect Materials Sampled: linoleum, mastic, duct tape, spray applied acoustic, ceiling tile

**Asbestos-Containing Materials Found:**

- 1) **Brown Spray Applied Acoustic** - Type: Friable Location: Fireside room, Youth chapel  
Asbestos Content: 5 to 30 percent Chrysotile asbestos, Trace Actinolite asbestos
- 2) **White Spray Applied Acoustic** - Type: Friable Location: North Passage, North Hall  
Asbestos Content: 5 to 10 percent Chrysotile asbestos

Building No.: 18

Building Name: **Church (Office Section South of Youth Chapel)**

Suspect Materials Sampled: spray applied acoustic, ceiling tile, fireproofing, duct tape

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: South Passage  
Asbestos Content: 10 to 20 percent Chrysotile asbestos

Building No.: 19

Building Name: **Paulin Hall**

Suspect Materials Sampled: spray applied acoustic, floor tile, mastic, linoleum, joint and elbow packing

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: lobby, throughout the building in various rooms  
Asbestos Content: 15 to 20 percent Chrysotile asbestos
- 2) **Brown Joint and Elbow Packing** - Type: Friable Location: throughout building on fiberglass insulated pipes in ceiling plenum  
Asbestos Content: 1 to 10 percent Chrysotile asbestos
- 3) **12" x 12" Floor Tile and Mastic** - Type: Nonfriable Location: throughout building  
Asbestos Content: 1 to 20 percent Chrysotile asbestos
- 4) **Green Linoleum and Mastic** - Type: Nonfriable Location: 2nd Floor: Room 201  
Asbestos Content: 30 to 35 percent Chrysotile asbestos

Building No.: 20

Building Name: **Pacific Auditorium**

Suspect Materials Sampled: spray applied acoustic, exterior plaster, interior plaster, floor tile, pipe covering

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Corridors, Rooms 40, 50, 60a, 103, 110, 113, 119  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 2) **Pipe Covering** - Type: Friable Location: Crawlspace, inside walls, Room 50  
Asbestos Content: 55 to 70 percent Chrysotile asbestos
- 3) **Joint and Elbow Packing** - Type: Friable Location: Crawlspace, inside walls, Room 50  
Asbestos Content: 55 to 70 percent Chrysotile asbestos
- 4) **Interior Plaster** - Type: Nonfriable Location: Basement  
Asbestos Content: Trace Chrysotile asbestos

Building No.: 22

Building Name: **Public Safety**

Suspect Materials Sampled: linoleum, floor tile, mastic, wall and ceiling plaster, exterior stucco

**Asbestos-Containing Materials Found:**

- 1) **Beige Linoleum & Mastic** - Type: Nonfriable Location: Restroom  
Asbestos Content: 25 to 30 percent Chrysotile asbestos
- 2) **9" x 9" Brown Vinyl Floor Tile** - Type: Nonfriable Location: file, storage, tool room  
Asbestos Content: 5 to 20 percent Chrysotile asbestos
- 3) **Ceiling Plaster & Paint** - Type: Nonfriable Location: throughout building  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 23

Building Name: **Chan Shun Hall**

Suspect Materials Sampled: fireproofing, floor tile, mastic, linoleum, transite panels, exterior stucco

**Asbestos-Containing Materials Found:**

- 1) **Transite Panels** - Type: Nonfriable Location: 3rd floor: Chemistry  
Asbestos Content: 30 to 35 percent Chrysotile asbestos

Building No.: 24

Building Name: **Davidian Hall**

Suspect Materials Sampled: Spray-applied acoustic

**Asbestos-Containing Materials found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: 2nd Floor: Corridor  
Asbestos Content: 10 to 15 percent Chrysotile asbestos

Building No.: 26

Building Name: **Dining Commons**

Suspect Materials Sampled: spray applied acoustic, linoleum, mastic, ceiling tile, joint packing, exterior stucco, interior plaster, and wallboard

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Dining and Banquet Rooms  
Asbestos Content: 15 to 20 percent Chrysotile asbestos
- 2) **Joint and Elbow Packing Material** - Type: Friable Location: food Storage, mechanical room  
Asbestos Content: 1 to 10 percent Chrysotile asbestos
- 3) **Button Wallboard** - Type: Friable Location: Inside walls  
Asbestos Content: 1 to 5 percent Actinolite asbestos
- 4) **Exterior Stucco** - Type: Nonfriable Location: Entire exterior covering  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 27

Building Name: **Rasmussen Art Gallery**

Suspect Materials Sampled: Linoleum, mastic

NO ASBESTOS-CONTAINING MATERIALS FOUND

Building No.: 28

Building Name: **Library**

Suspect Materials Sampled: Spray applied acoustic, interior plaster, exterior plaster, floor tile, mastic, fire

door core, duct insulation, ceiling tile

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic (Plaster)** - Type: Friable Location: Basement & First Floor  
Asbestos Content: 5 to 20 percent Chrysotile asbestos
- 2) **Spray Applied Acoustic (Sheetrock)** - Type: Friable Location: Entry 2nd Floor  
Asbestos Content: 10 to 15 percent Chrysotile asbestos
- 3) **Fire Door Core** - Type: Friable Location: Inside fire rated doors  
Asbestos Content: 50 to 55 percent Chrysotile asbestos
- 4) **Duct Insulation** - Type: Friable Location: Stairwell plenum, all floors  
Asbestos Content: 25 to 55 percent Chrysotile asbestos
- 5) **Spray Applied Acoustic (Plaster)** - Type: Friable Location: Tech Services & Media Services  
Asbestos Content: 3 to 5 percent Chrysotile asbestos
- 6) **Spray Applied Acoustic (Plaster)** - Type: Friable Location: Information Technology (I.T.)  
Asbestos Content: 3 to 5 percent Chrysotile
- 7) **Sheetrock & Joint Compound** Location: Information Technology (I.T.) hallway (Check with Plant Services)  
Asbestos Content: 1 to 2 percent
- 8) **Exterior Stucco** - Type: Non Friable Location: Penthouse exterior  
Asbestos Content: 3 to 5 percent Chrysotile Asbestos
- 9) **Thermal System Insulation Debris** - Type: Friable Location: Pipe Chases accessed from main stairwell  
Asbestos Content: 5 to 10 percent Amosite, 3 to 5% Chrysotile

Building No.: 31

Building Name: **Development/Alumni Office**

Suspect Materials Sampled: Insulation, linoleum, interior plaster, ceiling plaster, transite pipe

**Asbestos-Containing Materials Found:**

- 1) **Linoleum and Mastic** - Type: Nonfriable Location: M-W Restrooms  
Asbestos Content: 15 to 20 percent Chrysotile asbestos
- 2) **Transite Pipe** - Type: Nonfriable Location: Outside  
Asbestos Content: 25 to 30 percent Chrysotile asbestos

Building No.: 32

Building Name: **Business Office**

Suspect Materials Sampled: spray applied acoustic, pipe covering, linoleum, attic insulation

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Basement: storage, 1st floor: offices  
Asbestos Content: 5 to 25 percent Chrysotile asbestos
- 2) **Pipe Covering** - Type: Friable Location: Crawlspace  
Asbestos Content: 40 to 85 percent Chrysotile asbestos
- 3) **Joint and Elbow Packing** - Type: Friable Location: Crawlspace  
Asbestos Content: 70 to 75 percent Chrysotile asbestos

Building No.: 33

Building Name: **West Hall –Education**

Suspect Materials Sampled: spray applied acoustic, linoleum, mastic

**Asbestos-Containing Materials Found:**

- 1) **White Linoleum** - Type: Nonfriable Location: Restrooms  
Asbestos Content: 20 to 25 percent Chrysotile asbestos

Building No.: 33

Building Name: **West Hall Annex**

Suspect Materials Sampled: Floor tile, ceiling tile, linoleum, mastic, interior plaster, pipe covering, exterior stucco

**Asbestos-Containing Materials Found:**

- 1) **Pipe Covering** - Type: Friable Location: Crawlspace, inside walls  
Asbestos Content: 55 to 70 percent Chrysotile asbestos
- 2) **Joint and Elbow Packing** - Type: Friable Location: Crawlspace, inside walls  
Asbestos Content: 55 to 60 percent Chrysotile asbestos
- 3) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: Rooms 200, 202, Radio Room  
Asbestos Content: 5 to 10 percent Chrysotile asbestos
- 4) **Exterior Stucco** - Type: Nonfriable Location: Entire exterior coating  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 5) **Interior Plaster/Paint** - Type: Nonfriable Location: First floor interior, walls and ceiling  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 35

Building Name: **Stauffer Hall -English Department**

Suspect Materials Sampled: spray applied acoustic, floor tile, mastic, interior plaster, exterior plaster, pipe covering, duct insulation

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Reading room, career room, rooms A&B  
Asbestos Content: 1 to 20 percent Chrysotile asbestos
- 2) **Pipe Covering** - Type: Friable Location: Crawlspace  
Asbestos Content: 50 to 55 percent Chrysotile asbestos
- 3) **Joint and Elbow Packing** - Type: Friable Location: Crawlspace,  
Asbestos Content: 45 to 50 percent Chrysotile asbestos
- 4) **Duct Insulation** - Type: Friable Location: Crawlspace  
Asbestos Content: 80-85 percent Chrysotile asbestos
- 5) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: Career Room  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 37

Building Name: **Pacific Studio**

Suspect Materials Sampled: Linoleum, mastic, spray applied acoustic, interior plaster, floor tile

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Throughout building Asbestos

- Content: 1 to 5 percent Chrysotile asbestos
- 2) **Red Linoleum** - Type: Nonfriable Location: Entrance Hall, Howell Distributors  
Asbestos Content: 30 to 35 percent Chrysotile asbestos

Building No.: 38

Building Name: **Newton Hall**

Suspect Materials Sampled: Floor tile, mastic, linoleum, ceiling plaster, spray-applied acoustic, ceiling tile, wall plaster, pipe covering,

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: throughout Building  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 2) **White/Gray Pipe Covering** - Type: Friable Location: Steam Tunnel  
Asbestos Content: 40 to 60 percent Amosite asbestos
- 3) **Joint and Elbow Packing** - Type: Friable Location: Steam Tunnel,  
Asbestos Content: 35 to 40 percent Chrysotile asbestos, 5 to 15 percent Amosite asbestos
- 4) **Plaster and Paint** - Type: Nonfriable Location: Lobby Entrance,  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 5) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: throughout building  
(under carpet)  
Asbestos Content: 5 to 10 percent Chrysotile asbestos
- 6) **12" x 12" Floor Tile and Mastic** - Type: Nonfriable Location: Dean's Apt.,  
Janitor & Storage closets  
Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 7) **Linoleum and Mastic** - Type: Nonfriable Location: Dean's Apt., Janitor &  
Storage closets  
Asbestos Content: 15 to 20 percent Chrysotile asbestos

Building No.: 39

Building Name: **Grainger Hall**

Suspect Materials Sampled: Spray applied acoustic, floor tile, mastic, linoleum, interior plaster, paint, and attic insulation

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Rooms 107, 129, 207, 229, 307, 329  
Asbestos Content: 5 to 20 percent Chrysotile asbestos
- 2) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: throughout building  
Asbestos Content: 1 to 10 percent Chrysotile asbestos

Building No.: 41

Building Name: **Irwin Hall**

Suspect Materials Sampled: floor covering, interior plaster, exterior plaster, suspect debris

**Asbestos-Containing Materials Found:**

- 1) **Exterior Stucco** - Type: Nonfriable Location: Exterior Stucco  
Asbestos Content: 1 to 5 percent Chrysotile asbestos



Building No.: 42

Building Name: **Public Relations (Old Consumer & Family Sciences, N. End Graf Hall)**

Suspect Materials Sampled: Pipe covering, linoleum, mastic, interior plaster

**Asbestos-Containing Materials Found:**

**Graf Hall**

- 1) **Pipe Covering** - Type: Friable Location: 1st Floor: Room B  
Asbestos Content: 40 to 80 percent Chrysotile asbestos
- 2) **Joint and Elbow Packing** - Type: Friable Location: 1st Floor: Room B  
Asbestos Content: 35 to 50 percent Chrysotile asbestos
- 3) **Yellow Linoleum and Mastic** - Nonfriable Location: 1st Floor: Room C  
Asbestos Content: 35 to 40 percent Chrysotile asbestos
- 4) **Brown/White Linoleum** - Type: Nonfriable Location: 2nd Floor: Storage room  
Asbestos Content: 35 to 40 percent Chrysotile asbestos

**Ambs Hall**

- 1) **Pipe Covering** - Type: Friable Location: Crawlspace  
Asbestos Content: 40 to 90 percent Chrysotile asbestos
- 2) **9" x 9" Vinyl Floor Tile** - Type: Friable Location: 2nd floor kitchen/pantry, 3rd floor kitchen, bathroom Asbestos Content: 1 to 5 percent Chrysotile asbestos
- 3) **Exterior Stucco** - Type: Nonfriable Location: Exterior surfaces  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 44

Building Name: **Graf Hall, Radio Station (KNDL)**

Suspect Materials Sampled: Spray applied acoustic, linoleum, mastic, floor tile, pipe covering, interior plaster, and exterior plaster

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: 1st floor apartment, lobby, reception  
Asbestos Content: 20 to 25 percent Chrysotile asbestos

Building No.: 45

Building Name: **Dauphinee Chapel**

Suspect Materials Sampled: spray applied acoustic, pipe covering, wall plaster, exterior plaster

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Chapel Sanctuary  
Asbestos Content: 5 to 10 percent Chrysotile asbestos
- 2) **Pipe Covering** - Type: Friable Location: Inside walls and mechanical rooms  
Asbestos Content: 50 to 55 percent Chrysotile asbestos

Building No.: 46

Building Name: **Andre Hall**

Suspect Materials Sampled: Pipe covering, floor tile, mastic, linoleum, interior plaster, and exterior paint

**Asbestos-Containing Materials Found:**

- 1) **9" x 9" Vinyl Floor Tile** - Type: Nonfriable Location: Throughout building under carpet  
Asbestos Content: 10 to 15 percent Chrysotile asbestos
- 2) **Red/White Linoleum** - Type: Nonfriable Location: Stairwell to Recreation room

- 3) Asbestos Content: 5 to 10 percent Chrysotile asbestos  
Exterior Paint - Type: Nonfriable Location: Entire exterior of building  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 47

Building Name: **Winning Hall**

Suspect Materials Sampled: Spray applied acoustic, exterior stucco, floor tile, mastic, pipe covering, duct insulation

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic - Type**: Friable Location: Throughout south wing  
Asbestos Content: 10 to 20 percent Chrysotile asbestos
- 2) **Pipe Covering - Type**: Friable Location: Steam tunnel, mechanical room  
Asbestos Content: 60 to 65 percent Chrysotile asbestos
- 3) **12" x 12" Floor Tile - Type**: Nonfriable Location: Throughout building  
Asbestos Content: Trace Chrysotile asbestos

Building No.: 48

Building Name: **Preschool/Shed**

Suspect Materials Sampled: Linoleum, mastic, ceiling tile

NO ASBESTOS-CONTAINING MATERIALS FOUND

Building No.: 49

Building Name: **Farm Buildings**

Suspect Materials Sampled: Interior plaster, exterior plaster, floor tile, linoleum, mastic, pipe covering,

**Asbestos-Containing Materials Found:**

- 1) **Pipe Covering - Type**: Friable Location: Old Creamery attic, men's locker room, boiler room  
Asbestos Content: 60 to 75 percent Chrysotile asbestos
- 2) **Linoleum - Type**: Nonfriable Location: Tractor barn office and tool room  
Asbestos Content: 15 to 35 percent Chrysotile asbestos

Building No.: 51

Building Name: **Physical Plant**

Suspect Materials Sampled: Ceiling tile, linoleum, mastic, debris, exterior paint

**Asbestos-Containing Materials Found:**

- 1) **Green Linoleum - Type**: Nonfriable Location: Physical plant, women's restroom  
Asbestos Content: 30 to 35 percent Chrysotile asbestos
- 2) **Silver Paint - Type**: Nonfriable Location: Auto Body Shop exterior  
Asbestos Content: Trace Chrysotile asbestos

Building No.: 52

Building Name: **Mobil Manor Washette**

NO SUSPECT MATERIALS FOUND

Building No.: 53

Building Name: **Landscape Office**

Suspect Materials Sampled: Linoleum, mastic, spray applied acoustic, interior plaster, exterior plaster

NO ASBESTOS-CONTAINING MATERIALS FOUND

Building No.: 54

Building Name: **Court Place Apartments**

Suspect Materials Sampled: Linoleum, mastic, ceiling plaster, wall plaster

**Asbestos-Containing Materials Found:**

- 1) **Yellow Linoleum** - Type: Nonfriable Location: Kitchen, restrooms of 8 older units  
Asbestos Content: 45 to 50 percent Chrysotile asbestos
- 2) **Wall Plaster/Ceiling Plaster** - Type: Nonfriable Location: throughout each unit  
Asbestos Content: Trace Chrysotile asbestos

Building No.: 55

Building Name: **Nichol Hall**

Suspect Materials Sampled: Spray applied acoustic, linoleum, mastic, duct tape, transite pipe, ceiling plaster

**Asbestos-Containing Materials Found:**

- 1) **Spray Applied Acoustic** - Type: Friable Location: Throughout building  
Asbestos Content: 10 to 15 percent Chrysotile asbestos
- 2) **Linoleum** - Type: Nonfriable Location: Dorm bathrooms, kitchen, laundry rm, mail rm  
Asbestos Content: 20 to 25 percent Chrysotile asbestos
- 3) **Transite Pipe** - Type: Nonfriable Location: Buried outside  
Asbestos Content: 35 to 40 percent Chrysotile asbestos
- 4) **Exterior Stucco** - Type: Nonfriable Location: Patio ceiling  
Asbestos Content: Trace Chrysotile asbestos

Building No.: 56

Building Name: **McReynolds Hall**

Suspect Materials Sampled: Spray applied acoustic, linoleum, mastic, and interior plaster

**Asbestos-Containing Materials Found:**

- 1) **Green Linoleum** - Type: Nonfriable Location: Dorm restrooms, kitchen, Janitor's closet, laundry room  
Asbestos Content: 1 to 5 percent Chrysotile asbestos

Building No.: 57

Building Name: **Flight Center**

Suspect Materials Sampled: Spray applied acoustic, ceiling tile, linoleum, mastic, attic insulation, duct tape

**Asbestos-Containing Materials Found:**

- 1) **Brown Linoleum** - Type: Nonfriable Location: Furnace Room  
Asbestos Content: 40 to 45 percent Chrysotile asbestos

Building Name: **Sewer Plant**

Suspect Materials Sampled: Exterior Stucco

NO ASBESTOS-CONTAINING MATERIALS FOUND

Building Name: **Physical Education Equipment – Storage Bldg.**

NO SUSPECT MATERIALS FOUND

Building Name: **Steam Tunnels**

Suspect Materials Sampled: Pipe Covering, Joint and Elbow Packing

**Asbestos-Containing Materials Found:**

- 1) **Pipe Covering** - Type: Friable Location: Throughout one mile of steam tunnel  
Asbestos Content: 40 to 60 percent Chrysotile asbestos
- 2) **Joint and Elbow Packing** - Type: Friable Location: Throughout one mile of steam tunnel  
Asbestos Content: 40 to 60 percent Chrysotile asbestos

Building Name: **Albion Biology Station**

Suspect Materials Sampled: Linoleum, mastic, spray applied acoustic, attic insulation, wallboard material

**Asbestos-Containing Materials Found:**

- 1) **Linoleum and Mastic** - Type: Nonfriable Location: All Cabins  
Asbestos Content: 10 to 35 percent Chrysotile asbestos